

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

54244C/31 DAIDO TOKUSHOKO KK	M27 14.12.78-JA-153683 (16.06.80) C22c-38/34	DAIZ 14.12.78 *J5 5079-857	M(13-A, 27-A4, 27-A4C, 27-A4S).
Iron alloy with good molten zinc corrosion resistance - contains carbon, silicon, manganese, chromium, nickel, molybdenum, tungsten, niobium, titanium, vanadium and aluminium			1 3 4
Relatively low cost alloy with high resistance to corrosion due to molten Zn, which consists of <0.40% C, 1.50-3.50% Si, <2.0% Mn, 3.0-20.0% Cr, ≥ 1 of <5.0% Ni, <5.0% Mo, <5.0% W, <2.0% Nb, <1.0% Ti, <1.0% V, and <1.0% Al and the balance Fe.			
Alloy is used to mfr. a vessel, transportation pump or pipe, immersion roll for producing galvanised steel plates, or stirring jig contacting molten Zn. (5pp53)			
			J55079857

420-70
X 420-109

1